



After completing the under-buoy hose repair and reconnecting the hose to the Floating Storage Offloading (FSO) vessel, [Hindustan Oil Exploration Company Limited](#) has begun gas sales from its B-80 field with D2 well, located in western offshore.

Since the under-buoy hose was discovered to be damaged in the middle of July 22, gas sales from this field have had to be discontinued. Due to unfavourable weather, a previous attempt to repair proved unsuccessful.

With the aid of experts in Dubai and the assistance of the local diving crew, the company had constructed an additional spool/clamp and finished the repair operation.

Well D-2 produces gas, which is processed at KGB Offshore Installation before being transferred over the ONGC pipeline network to its Hazira Gas Processing facility.

Site Moved. Visit our New Website

We have moved this news site from this URL

to <https://www.newprojectstracker.com/capex-news> .

Visit this site for regular updates

Buy Latest Research Reports